ASBESTOS ASSES. SURVEY

H-K Building #: 18
Project Number: 0980193E
Project: G. HEILEMAN BREWERY "E"
Date Inspected: 03/27/89
Inspector: CURT BAXTER

Building Number: 18
Building Name: SALES OFFICE

SEATTLE, WASHINGTON 98134
Building Type: OFFICE
Year Constructed: UNKN

******* AREA NUMBER: 01	AREA DESCI	RIPTIO	N: 1st Floor	AREA AV	****					
LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	UNITS OUANTITY MEASUR	EXP	PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL
north & center offices & reception area	01-356256	0%	acoustical tile	OMG	1643 sq.ft.	 				
south & west side perimeter offices	01-356256 01-356257 01-356258		acoustical tile	OMG	664 sq.ft.					
ladies' restroom	02-356259	0%	drop or lay-in panel	OMG	36 sq.ft.				•	
men's restroom	02-356259		drop or lay-in panet	OMG	42 sq.ft.					
east corridor from receiving area	02-356259		drop or lay-in panel	OMG	80 sq.ft.					
receiving area	02-356259		drop or lay-in panel	OMG	432 sq.ft.					
east offices & men's restrooom	02-356259 02-356260 02-356261	0% 0% 0%	drop or lay-in panel	OMG	372 sq.ft.					
bar/saloon area	03-356724 03-356725 03-356726	0% 0% 0%	drop or lay-in panel	OMG	600 sq.ft.					

AREA COMMENTS

AREA # 01 TOTAL \$0 \$0 \$0

\$0 BUILDING # 18 TOTAL

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 43

H-K Building #: 21

Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/21/89 Inspector: TIM SWARTZ Building Number: 21/22

Building Name: BREWHOUSE/STOCK CELLARS

SEATTLE, WASHINGTON
Building Type: BREW/STOCK

Year Constructed: 1948

****** AREA NUMBER: 01	AREA DESC	RIPTIO	N: Ground Floor-Part #21-Spent (Grain R	oom AREA AVE	RAGE % AS	ESTOS: 22	X ·	******	****
LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	UNITS O		EXP POT PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
above caustic tank & along east wall	00-356573		pipe covering	OMA	50 ft. 4 in.		R 27 111	\$446	\$279	\$77
southeast area-by caustic tank	00-356577	0%	pipe covering	OHA	30 ft. 8 in.	O.D. DW		1		
above caustic tank & along south wall	00-356581	10%	wrapped cardboard/paper pipe	OMA	42 ft. 8 in.	O.D. DW	27 111	\$594	\$425	\$1,0
center E to W-along beam-at ceiling	00-356585	15%	wrapped cardboard/paper pipe	AHO	25 ft. 6 in.	O.D. DW	27 111	\$324	\$203	\$ 5
along east wall-near ceiling	00-356585	15%	wrapped cardboard/paper pipe	AMO	70 ft. 4 in.	O.D. DW	27 111	\$624	\$391	\$1,0
near north entrance	00-356585	15%	wrapped cardboard/paper pipe	AMO	26 ft. 8 in.	O.D. DW	27 111	\$368	\$263	\$6
above caustic tank & along east wall	00-356585	15%	wrapped cardboard/paper pipe	OMA	30 ft. 4 in.	O.D. DW	27 111	\$268	\$167	\$4
center N to S-along beam-at ceiling	00-356585	15%	wrapped cardboard/paper pipe	AMO	12 ft. 4 in.	O.D. DW	27 111	\$107	\$67	\$1
above caustic tank & along east Wall	12-356574	15%	mjp on pipe covering	OMA	20 4 in. 0.D	. HPS	R 27 111	\$562	\$312	\$8
	12-356575	10%					27 111			
	12-356576	25%					27 111	i		
southeast area-by caustic tank	13-356578	0%	mjp on pipe covering	OMA	3 8 in. 0.D	. DW	27 111	\$144	\$85	\$2
•	13-356579	0%					27 111	į		
	13-356580	0%	1				27 111	ļ		
above caustic tank & along south wall	14-356582	35%	mjp on wrapped cardboard/paper	OMA	70 8 in. O.D	. DW	27 111	\$3,369	\$1,981	\$5,3
	14-356583	40%	1				27 111		•	•
	14-356584	50%					27 111			
near north entrance	15-356586	50%	imip on wrapped cardboard/paper	OMA	2 8 in. 0.0	. DW	27 111	\$96	\$57	\$
long east wall-near ceiling	15-356586	50%	mjp on wrapped cardboard/paper	AMO	10 4 in. O.D	. DW	27 111	\$281	\$156	\$
bove caustic tank & along east wall	15-356586		mjp on wrapped cardboard/paper	OMA	6 4 in. O.D	. DW	27 111	\$169	- \$94	\$
center E to W-along beam-at ceiling	15-356586		mjp on wrapped cardboard/paper	OMA	1 6 in. 0.0	. DW	27 111		\$23	
center N to S-along beam-at ceiling	15-356586		mip on wrapped cardboard/paper	AMO	1 4 in. 0.0	. DW	27 111	\$28	\$16	
	15-356587	60%	1				27 111		•	
	15-356588	60%	}				27 111			
	.1		L					<u> </u>		
AREA COMMENTS						4254 # 4	1 TOTAL	\$7,419	\$4,519	\$11,

The materials are in fair condition with minor localized contact and water damage. The materials are approximately 5' to 14' from the floor. At a minimum, it is recommended that the materials be properly repaired and monitored. If removal is planned, gross removal procedures are recommended. This appears to be a medium traffic area.

******	*** AREA NUMBER: 02	AREA DESCRIPTION: Ground Floor	AREA AVERAGE % ASBESTOS: 27%	*****
L				

LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M COOE	YTITHAUD	UNITS OF MEASURE	PIPE ID	 PL	 REPLACEMENT COSTS	TOTAL COSTS
part 21-brew kettle rm-under S kettle part 21-brew kettle rm-under S kettle	00-356573 00-356573		pipe covering pipe covering	OMA OMA		ft. 4 in. 0.0 ft. 6 in. 0.0			\$446 \$41	\$1,160 \$106

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 44

H-K Building #: 21 Project Number: 0980193E

Project: Q. HEILEMAN BREWERY "E"
Date Inspected: 03/21/89
Inspector: TIM SWARTZ

Building Number: 21/22
Building Hame: BREWHOUSE/STOCK CELLARS
SEATTLE, WASHINGTON
Building Type: BREW/STOCK
Year Constructed: 1948

-										
part 21-west wall	00-356573		pipe covering	OHA	20 ft. 6 in. O.D.			\$260	\$162	\$422
stairwell in part 21	00-356573		pipe covering	OHA	5 ft. 4 in. 0.D.			\$45	\$28	\$73
stairwell in part 21	00-356573		pipe covering	OMA	3 ft. 6 in. D.D.			\$39	\$24	\$63
part 21-brew kettle rm-under N kettle	00-356573		pipe covering	OHA	45 ft. 4 in. O.D.			\$401	\$251	\$652
part 21-brew kettle rm-under N kettle	00-356573		pipe covering	OHA	16 ft. 6 in. O.D.			\$208	\$130	\$338
part 21-against south wall-along ceiling	00-356573		pipe covering	OMA	20 ft. 4 In. O.D.			\$178	\$112	\$290
part 21-brew kettle rm-along east wall	00-356573		pipe covering	OMA	45 ft. 4 in. O.D.	HPS/R	26 111	\$401	\$251	\$652
part 22-cellar H stock-along east wall	00-356573		pipe covering	OHA	180 ft. 4 in. O.D.	HPS/R	26 111	\$1,606	\$1,004	\$2,610
part 22-cellar H stock-along east wall	00-356573	25%	pipe covering	OMA	180 ft. 8 in. O.D.	HPS/R	26 111	\$2,547	\$1,820	\$4,367
part 21-west wall	00-356573	25%	pipe covering	OMA	40 ft. 8 in. O.D.	HPS/R	26 111	\$566	\$404	\$970
part 21-brew kettle room-catwalk	00-356573	25%	pipe covering	OMA	130 ft. 4 in. O.D.	HPS/R	26 111	\$1,160	\$725	\$1,885
part 21-brew kettle room-catwalk	00-356573	25%	pipe covering	OHA	88 ft. 6 in. O.D.	HPS/R	26 111	\$1,142	\$714	\$1,856
part 21-west wall	00-356573	25%	pipe covering	OMA	40 ft. 4 in. O.D.	HPS/R	26 111	\$357	\$223	\$580
stairwell in part 21	00-356573		pipe covering	OMA	3 ft. 10 in. 0.D	HPS/R	26 111	\$57	\$42	\$99
pt 21-brew kettle rm-catwalk-ctr&E wall	00-356577		pipe covering	OMA	35 ft. 4 in. O.D.	DW				
pt 21-brew kettle rm-catwalk-ctr&E wall	00-356577	0%	pipe covering	AMO	10 ft. 6 in. O.D.	DW	1			
part 21-against south wall-along ceiling	00-356577	0%	pipe covering	OMA	25 ft. 8 in. O.D.	DW	1			
part 21-brew kettle rm-northeast area	00-356589	40%	pipe covering	, OMA	25 ft. 6 in. O.D.	PL	26 111	\$324	\$203	\$527
part 21-brew kettle rm-kettle at N end	01-356463	50%	boiler/tank insulation	OMB	830 sq.ft.		26 111	\$23,448	\$18,783	\$42,231
	01-356464	35%					26 111			1
	01-356465	35%					26 111			
part 21-brew kettle rm-kettle at S end	02-356466	40%	boiler/tank insulation	OMB	830 sq.ft.		26 111	\$23,448	\$18,783	\$42,231
F-1.7 2. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.	02-356467	40%					26 111			
	02-356468	40%	1				26 111			1
part 21-brew kettle room-catwalk	12-356574	15%	mjp on pipe covering	OMA	16 4 in. O.D.	HPS/R	26 111	\$449	\$250	\$699
part 22-cellar H stock-along east wall	12-356574	15%	mjp on pipe covering	OMA	4 8 in. O.D.	HPS/R	26 111	\$193	\$113	\$306
part 21-brew kettle rm-under S kettle	12-356574	15%	mjp on pipe covering	OHA	20 4 in. O.D.		26 111	\$562	\$312	\$874
part 21-west wall	12-356574	15%	mjp on pipe covering	OMA	5 4 in. O.D.		26 111	\$140	\$78	\$218
stairwell in part 21	12-356574	15%	mjp on pipe covering	OMA	1 10 in. o.D.		26 111	\$63	\$39	\$102
part 22-cellar H stock-along east wall	12-356574	15%	mjp on pipe covering	OMA	4 4 in. O.D.		26 111	\$112	\$62	\$174
part 21-against south wall-along ceiling	12-356574	15%	mjp on pipe covering	OMA	4 4 in. O.D.		26 111	\$112	\$62	\$174
part 21-brew kettle rm-under N kettle	12-356574	15X	mjp on pipe covering	OHA	15 4 in. O.D.	HPS/R	26 [11]	\$421	\$234	\$655
part 21-west wall	12-356574	15%	mjp on pipe covering	OMA	4 8 in. O.D.	HPS/R	26 111	\$193	\$113	\$306
part 21-brew kettle room-catwalk	12-356574	15%	mlp on pipe covering	OMA	20 6 in. O.D.	HPS/R	26 111	\$774	\$454	\$1,228
stairwell in part 21	12-356574	15%	mip on pipe covering	OMA	1 6 in. O.D.	HPS/R	26 111	\$39	\$23	\$62
stairwell in part 21	12-356574	15%	mip on pipe covering	OMA	1 4 in. O.D.	HPS/R	26 1111	\$28	\$16	\$44
part 21-brew kettle rm-along east wall	12-356574		mjp on pipe covering	OMA	10 4 in. O.D.	HPS/R	26 111	\$281	\$156	\$437
part 21-west wall	12-356574	15%	mjp on pipe covering	OMA	8 6 in. O.D.	HPS/R	26 111	\$309	\$182	\$491
part 21 hast hart	12-356575	10%					26 111			1
	12-356576	25%	1				26 111			1
pt 21-brew kettle rm-catwalk-ctr&E wall	13-356578		mip on pipe covering	OMA 1	8 4 in. O.D.	DW	26 111	\$225	\$125	\$350
part 21-against south wall-along ceiling	13-356578		mjp on pipe covering	OMA	2 8 in. 0.D.	DW	26 111	\$96	\$57	\$153
part at against south mate atong certifig	13-356579	0%	,			- **	26 111	2.0		
1	13-356580	0%					26 111			1
part 21-brew kettle rm-northeast area	16-356590		mjp on pipe covering	OMA	12 6 in. 0.D.	PL	26 111	\$464	\$273	\$737
Part Zishiem Kettte tillshortheast alea	16-356591	0%	mile ou bibe cover ma	O IA	12 0 111, 0.0.		26 111		72.5	
	16-356592	40%	1				26 111			1
21-brow keetle emecaustic took	17-356593		boiler/tank insulation	OMB	90 sq.ft.		-9			
part 21-brew kettle rm-caustic tank	בענטנני זו	Ų.A	porter/tank madeacton	0.10	70 34.16.		l			,

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 45

ASRESTOS ASSES

SURVEY

H-K Building w: 21 'Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/21/89 Inspector: TIM SWARTZ Building Number: 21/22

Building Name: BREWHOUSE/STOCK CELLARS
SEATTLE, WASHINGTON

Building Type: BREW/STOCK Year Constructed: 1948

part 21-brew kettle rm-3M CIP tank-north	17-356594 17-356595 18-356596 18-356597 18-356598	0% 0% 40% 50% 40%	boiler/tank insulation	ОМВ	86 sq.ft.	26 III 26 III 26 III	\$2,430	\$1,946	\$4,376
--	---	-------------------------------	------------------------	-----	-----------	----------------------------	---------	---------	---------

AREA COMMENTS

\$48,641 \$112,498 AREA # 02 TOTAL \$63,857

The materials are in fair to good condition with minor contact and water damage. The materials are approximately 1' to 10' from the floor. At a minimum, it is recommended that the materials be repaired and monitored. If removal is planned, extensive gross removal procedures are recommended. This appears to be a high traffic area.

*******	AREA NUMBER: 03	AREA DESCRIPTION: 2nd Floor-Part #21	AREA AVERAGE % ASBESTOS: 35%	***

LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	UNITS OF QUANTITY MEASURE	PIPE ID	EXP POT	PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
stairwell between 1st & 2nd floors	00-356472		pipe covering	OHA	20 ft. 4 in. O.D.			111	\$178		\$290
stairwell between 1st & 2nd floors	00-356472		pipe covering	AMO	8 ft. 10 in. 0.D			111	\$151	\$112	\$263
stairwell between 1st & 2nd floors	00-356472	30%	pipe covering	OHA	8 ft. 12 in. 0.D	HPS/R	26	111	\$176		\$311
kettle room-north area	00-356472	30%	pipe covering	OHA	140 ft. 4 in. O.D.			111	\$1,249		\$2,030
kettle room-north area	00-356472		pipe covering	OMA	16 ft. 6 in. O.D.			111	\$208	\$130	\$338
kettle room-north area	00-356472	30%	pipe covering	OMA	15 ft. 8 in. O.D.	HPS/R	26	111	\$212	\$152	\$364
kettle room-mezzanine-along south wall	00-356472	30%	pipe covering	OMA	10 ft, 12 in. 0.D	HPS/R	26	111	\$220	\$169	\$389
kettle room-mezzanine-along north wall	00-356472	30%	pipe covering	OHA	5 ft. 6 in. 0.D.	HPS/R	26	111	\$65	\$41	\$106
kettle room-hops storage	00-356472	30%	pipe covering	OHA	40 ft. 4 in. O.D.	HPS/R	26	111	\$357	\$223	\$580
kettle room-mezzanine-along south wall	00-356472	30%	pipe covering	AMO	10 ft. 10 in. 0.D	HPS/R	26	111	\$189	\$140	\$329
kettle room-mezzanine-along north wall	00-356472	30%	pipe covering	OMA	30 ft. 8 in. O.D.	HPS/R	26	111	\$424	\$303	\$727
kettle room-mezzanine-against east wall	00-356472	30%	pipe covering	OMA	18 ft. 8 in. O.D.	HPS/R	26	111	\$255	\$182	\$437
kettle room-mezzanine-against south wall	00-356476	40%	wrapped cardboard/paper pipe	OMA	10 ft. 8 in. O.D.	DW	26	111	\$141	\$101	\$242
kettle room-break room	00-356476	40%	wrapped cardboard/paper pipe	OHA	1 ft. 6 in. O.D.	DW	26	111	\$13	\$8	\$21
kettle room-break room	00-356476	40%	wrapped cardboard/paper pipe	AMO	10 ft. 8 in. o.D.	DW	26	111	\$141	\$101	\$242
kettle room-hops storage-northeast area	00-356476	40%	wrapped cardboard/paper pipe	AHO	10 ft. 6 in. O.D.	DW	26	111	\$130	\$81	\$211
stairwell between 1st & 2nd floors	04-356473	50%	mjp on pipe covering	OHA	6 4 in. O.D.	HPS/R	26	111	\$169	\$94	\$263
kettle room-north area	04-356473	50%	mjp on pipe covering	AMO	4 6 in. 0.D.	HPS/R	26	111	\$155	\$91	\$246
stairwell between 1st & 2nd floors	04-356473	50%	mjp on pipe covering	AMO	2 10 in. O.D.	HPS/R	26	111	\$125	\$78	\$203
kettle room-mezzanine-along north wall	04-356473	50%	mjp on pipe covering	OMA	6 6 in. O.D.	HPS/R	26	111	\$232	\$136	\$368
kettle room-mezzanine-along north wall	04-356473	50%	mjp on pipe covering	OMA.	5 8 (n. 0.D.	HPS/R	26	111	\$241	\$141	\$382
stairwell between 1st & 2nd floors	04-356473	50%	mjp on pipe covering	OMA	2 12 in. O.D.	HPS/R	26	111	\$152	\$95	\$247
kettle room-north area	04-356473	50%	mjp on pipe covering	OMA	12 4 in. O.D.	HPS/R		111	\$337	\$187	\$52
kettle room-hops storage-south area	04-356473	50%	mjp on pipe covering	OMA	12 4 in. O.D.	HPS/R		111	\$337	\$187	\$524
kettle room-north area	04-356473		mjp on pipe covering	OMA	3 8 in. O.D.	HPS/R		111	\$144	\$85	\$229
kettle room-mezzanine-against east wall	04-356473	50%	mjp on pipe covering	OMA	4 8 in. 0.D.	HPS/R		111	\$193		\$306
THE STATE OF THE BEST STATE OF THE STATE OF	04-356474	50%		T		0/1		111)	J.,.5	
•	04-356475	60%						iii	}		

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 46

ASBESTOS ASSES SURVEY

#-K Building #: 21

Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/21/89 Inspector: TIM SWARTZ Building Number: 21/22

Building Name: BREWHOUSE/STOCK CELLARS

SEATTLE, WASHINGTON
Building Type: BREW/STOCK Year Constructed: 1948

П	kettle room-break room	05-356477	60%	mjp on wrapped cardboard/paper	OHA	1 8 in. O.D.	DW	26 111	\$48	\$28	\$76
j	kettle room-break room	05-356477		mjp on wrapped cardboard/paper	OMA	2 6 in. O.D.	DW	26 111	\$77	\$45	\$122
		05-356478	50%	1				26 111			
- 1		05-356479	50%	l				26 111			
	kettle room-break room-whirlpool	06-356480		boiler/tank insulation	OMB	550 sq.ft.		26 111	\$15,538	\$12,446	\$27,984
- }	· ·	06-356481	10%	l .				26 111			
- 1		06-356482	40%					26 111			

AREA COMMENTS

AREA # 03 TOTAL \$21,857 \$38,354 \$16,497

The materials are in good condition with minor contact and water damage. The materials are approximately 1' to 18' from the floor. At a minimum, it is recommended the materials be repaired and monitored. If removal is planned, gross removal procedures are recommended. This appears to be a high traffic area.

*****	AREA NUMBER: 04	AREA DESCRIPTION	4: 3rd Floor-Part #21-Tank Bottom Room	AREA AVERAGE	% ASBESTOS: 32	* *******
		······································				
		SAMPLE	O&M	UNITS OF	PIPE EXP	REMOVAL REPLACEMENT TOTAL

LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	UNITS OF QUANTITY MEASURE	PIPE ID	EXP POT	PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
below mash tub	00-356495		pipe covering	OHA	55 ft. 4 in. O.D.		28	111	\$491	\$307	\$798
below mash tub	, 00-356495		pipe covering	AMO	35 ft. 6 in. O.D.			111	\$454	\$284	\$738
north of mash filter	00-356495		pipe covering	AHO	6 ft. 4 in. 0.D.			111]	\$54	\$33	\$87
south of mash filter	00-356495		pipe covering	OMA	10 ft. 8 in. O.D.			111	\$141	\$101	\$242
below adjunct cooker	00-356495		pipe covering	OHA	25 ft. 10 in. O.D			1111	\$472	\$349	\$821
below convertor tank	00-356495		pipe covering	OHA	30 ft. 6 in. O.D.			111	\$389	\$243	\$632
just northeast of caustic tank	00-356495		pipe covering	OMA	15 ft. 4 in. 0.D.			111]	\$134	\$84	\$218
just northeast of caustic tank	00-356495		pipe covering	OMA	5 ft. 6 in. O.D.			111	\$65	\$41	\$106
below convertor tank	00-356495		pipe covering	OMA	60 ft. 4 in. O.D.			111	\$535	\$335	\$870
below adjunct cooker	00-356495		pipe covering	AHO	55 ft. 6 in. O.D.			111	\$714	\$446	\$1,160
below adjunct cooker	00-356495		pipe covering	AMO	60 ft. 4 in. O.D.			111	\$535	\$335	\$870
behind caustic tank-against south wall	00-356495		pipe covering	AMO	16 ft. 8 ln. O.D.		28	111	\$226	\$162	\$388
behind caustic tank-against south wall	00-356499		wrapped cardboard/paper pipe	AMO	8 ft. 8 in. 0.D.			111	\$113	\$81	\$194
center E to W-along beam-near ceiling	00-356603	30%	pipe covering	OMA	90 ft. 6 in. O.D.	PL	28	111	\$1,168	\$730	\$1,898
east side-mash filter-near floor	00-356603		pipe covering	OHA	6 ft. 6 in. O.D.	PL.		111)	\$78	\$49	\$127
east side-mash filter-near floor	00-356603	30%	pipe covering	OHA	6 ft. 4 in. 0.D.	PL	28	111	\$54	\$33	\$87
east wall-near adjunct cooker-at floor	00-356603	30%	pipe covering	OMA	4 ft. 10 in. O.D	PL	28	111	\$75	\$56	\$131
below adjunct, convertor & mash tub tanks	00-356603	30%	pipe covering	OHA	60 ft. 10 in. 0.D	PL	28	111	\$1,132	\$838	\$1,970
east wall-near adjunct cooker-at floor	00-356603	30%	pipe covering	OHA .	22 ft. 6 in. O.D.	PL	28	111	\$286	\$178	\$464
convertor tank	07-356483	35%	boiler/tank insulation	OMB.	600 sq.ft.		28	1111	\$16,950	\$13,578	\$30,528
	07-356484	40%			·		28	1111	•	•	-
	07-356485	40%						111			
adjunct cooker	08-356486	40%	boiler/tank insulation	OMB	600 sq.ft.			111	\$16,950	\$13,578	\$30,528
	08-356487	40%	• • • • • • • • • • • • • • • • • • • •					iiil	,	0.0,0.0	,
	08-356488	40%						iiil			
mash tub	09-356489		boiler/tank insulation	ОМВ	600 sq.ft.			iiil	\$16,950	\$13,578	\$30,528
mount too	09-356490	50%		Q. (U	500 54.16.			iiil	0,750	4137310	-50,520

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 47

ASBESTOS ASSESS

SURVEY

N-K Building #: 21

Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/21/89 Inspector: TIM SWARTZ Building Number: 21/22

Building Name: BREWHOUSE/STOCK CELLARS

SEATTLE, WASHINGTON

Building Type: BREW/STOCK

Year Constructed: 1948

AREA AVERAGE % ASBESTOS: 30%

	09-356491	0%					28 111			
caustic tank	10-356492		boiler/tank insulation	OMB	500 sq.ft.		28 111	\$14,125	\$11,315	\$25,44
•	10-356493	50%					28 111			
	10-356494	50%	1		*		28 111			
below adjunct cooker	11-356496	40%	mjp on pipe covering	AHO	25 6 in. O.D.	HPS/R	28 111	\$967	\$568	\$1,53
below convertor tank	11-356496	40%	mjp on pipe covering	OMA	35 4 in. O.D.	HPS/R	28 111	\$983	\$546	\$1,52
Just northeast of caustic tank	11-356496	40%	mjp on pipe covering	OMA	2 6 in. O.D.	HPS/R	28 111	\$77	\$45	\$12
below mash tub	11-356496	40%	mjp on pipe covering	OMA	30 4 in. O.D.	HPS/R	28 111	\$843	\$468	\$1,31
below adjunct cooker	11-356496	40%	mjp on pipe covering	AHO	6 10 in. 0.D.	HPS/R	28 111	\$376	\$235	\$61
Just northeast of caustic tank	11-356496	40%	mip on pipe covering	OMA	8 4 in. O.D.	HPS/R	28 111	\$225	\$125	\$35
below adjunct cooker	11-356496	40%	mip on pipe covering	OHA	27 4 in. O.D.	HPS/R	28 111	\$758	\$421	\$1,17
south of mash filter	11-356496	40%	mlp on pipe covering	AHO	2 8 in. O.D.	HPS/R	28 111	\$96	\$57	\$1
below convertor tank	11-356496	40%	mjp on pipe covering	OMA	5 6 in. O.D.	HPS/R	28 111	\$193	\$114	\$30
below mash tub	11-356496	40%	mjp on pipe covering	OMA	14 6 in. O.D.	HPS/R	28 111	\$542	\$318	\$8
	11-356497	50%	1 "				28 111			
	11-356498	50%	(28 111			
below adjunct, convertor & mash tub tanks	21-356604	60%	mjp on pipe covering	OMA	10 10 in. O.D.	PL	28 111	\$626	\$391	\$1,0
center E to W-along beam-near ceiling	21-356604	60%	mlp on pipe covering	OHA	10 6 in. O.D.	PL	28 111	\$387	\$227	\$6
east wall-near adjunct cooker-at floor	21-356604	60%	mip on pipe covering	OMA	6 6 in. O.D.	PL	28 111	\$232	\$136	\$3
east wall-near adjunct cooker-at floor	21-356604	60%	mip on pipe covering	OHA	2 10 in. O.D.	PL	28 111	\$125	\$78	\$2
	21-356605	60%] "				28 111			
	21-356606	60%	i				28 111			

AREA COMMENTS

AREA NUMBER: 05

\$138,984 AREA # 04 TOTAL \$78,521 \$60,463

The materials are in fair condition with localized contact and water damage. The materials are approximately 1' to 10' from the floor. At a minimum, it is recommended that the materials be repaired and monitored. If removal is planned, extensive gross removal procedures are recommended. This appears to be a high traffic area.

LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	UNITS OF QUANTITY MEASURE	PIPE 10	EXP POT PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
north wall-by adjunct cooker	00-356495	30%	pipe covering	OMA	15 ft. 4 in. O.D.	HPS/R	27 111	'\$134	\$84	\$218
north wall-by adjunct cooker	00-356495	30%	pipe covering	AMO	10 ft. 8 in. O.D.	HPS/R	27 111	\$141	\$101	\$242
north wall-by adjunct cooker	00-356495	30%	pipe covering	OMA .	10 ft. 12 in. O.D	HPS/R	27 111	\$220	\$169	\$389
south wall-behind caustic tank	00-356495		pipe covering	OMA	30 ft. 6 in. 0.D.	HPS/R	27 111	\$389	\$243	\$632
south wall-behind caustic tank	00-356495		pipe covering	AMO	10 ft. 4 in. O.D.	HPS/R	27 111	\$89	\$56	\$145
south wall-behind caustic tank	00-356495		pipe covering	AMO	20 ft. 10 in. O.D	HPS/R	27 111	\$377	\$279	\$656
south wall-behind caustic tank	00-356499		wrapped cardboard/paper pipe	AMO	10 ft. 10 in. 0.D	HPS/R	27 111	\$189	\$140	\$329
next to mash tub	00-356603	30%	pipe covering	OMA	22 ft. 6 in. O.D.	PL	27 111	\$286	\$178	\$464
next to adjunct cooker	00-356603	30%	pipe covering	OMA	27 ft. 6 in. O.D.	PL	27 111	\$350	\$219	\$569
next to convertor tank	00-356603	30%	pipe covering	AMO	12 ft. 6 in. O.D.	PL	27 111	\$156	\$97	\$253
next to adjunct cooker	00-356603	30%	pipe covering	AMO	25 ft. 8 in. O.D.	PL	27 111	\$354	\$253	\$607

AREA DESCRIPTION: 3rd Floor-Part #21-Tank Top Room

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 48

06/09/89

ASRESTOS ASSESS SURVEY

H-K Building #: 21

Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/21/89 Inspector: TIM SWARTZ Building Number: 21/22

Building Name: BREWHOUSE/STOCK CELLARS SEATTLE, WASHINGTON

SEATTLE, WASHINGTO
Building Type: BREW/STOCK

Year Constructed: 1948

AREA AVERAGE % ASBESTOS: 42%

next to adjunct cooker	00-356603	30% pipe covering	OHA	12 ft. 4 in. O.D.		27 111	\$107	\$67	\$174
next to mash tub	00-356603	30% pipe covering	OMA	40 ft. 4 in. O.D.	PL	27 111	\$357	\$223	\$580
next to mash tub	00-356603	30% pipe covering	AMO	7 ft. 8 in. 0.D.		27 111	\$99	\$71	. \$170
next to convertor tank	00-356603	30% pipe covering	OMA	12 ft. 8 in. O.D.	PL	27 111	\$170	\$121	\$291
next to convertor tank	00-356603	30X pipe covering	OHA	12 ft. 4 in. O.D.	PL	27 111	\$107	\$67	\$174
north wall-by adjunct cooker	11-356496	40% mjp on pipe covering	OMA	5 4 in. 0.D.	HPS/R	27 111	\$140	\$78	\$218
south wall-behind caustic tank	11-356496	40% mjp on pipe covering	OHA	2 4 in. O.D.	HPS/R	27 111	\$56	\$31	\$87
south wall-behind caustic tank	11-356496	40% mjp on pipe covering	OHA	6 10 in. O.D.	HPS/R	27 111	\$376	\$235	\$611
north wall-by adjunct cooker	11-356496	40% mjp on pipe covering	OHA	1 8 in. O.D.	HPS/R	27 111	\$48	\$28	\$76
south wall-behind caustic tank	11-356496	40% mjp on pipe covering	OHA	2 6 in. 0.D.	HPS/R	27 111	\$77	\$45	\$122
	11-356497	50%		•		27 111			
	11-356498	50%				27 111			
south wall-behind caustic tank	20-356600	70% mjp on wrapped cardboard/paper	· OMA	6 10 in. O.D.	HPS/R	27 111	\$376	\$235	\$611
	20-356601	60X				27 111			
	20-356602	0%				27 111			
next to mash tub	21-356604	60% mjp on pipe covering	OMA	6 8 in. 0.0.	PL	27 111	\$289	\$170	\$459
next to convertor tank	21-356604	60% mjp on pipe covering	OHA	4 8 in. O.D.	PL	27 111	\$193	\$113	\$306
next to adjunct cooker	21-356604	60% mjp on pipe covering	OMA	6 4 in. 0.D.	PL	27 111	\$169	\$94	\$263
next to adjunct cooker	21-356604	60% mjp on pipe covering	OMA	8 8 in. O.D.	PL	27 111	\$385	\$226	\$611
next to mash tub	21-356604	60% mjp on pipe covering	OMA	8 6 in. 0.D.	PL	27 111	\$309	\$182	\$491
next to convertor tank	21-356604	60% mjp on pipe covering	OMA	2 4 in. 0.D.	PL	27 111	\$56	\$31	\$87
next to adjunct cooker	21-356604	60% mjp on pipe covering	OMA	12 6 in. O.D.	PL	27 111	\$464	\$273	\$737
next to mash tub	21-356604	60% mjp on pipe covering	AHO	12 4 in. 0.D.	PL	27 111	\$337	\$187	\$524
next to convertor tank	21-356604	60% mjp on pipe covering	OMA	4 6 in. O.D.	PL	27 111	\$155	\$91	\$246
*******	21-356605	60%				27 111			
	21-356606	60%				27 111			

AREA COMMENTS

AREA NUMBER: 06

AREA # 05 TOTAL \$6,955 \$4,387 \$11,342

The materials are in good condition with minor contact damage. The materials are approximately 1' to 12' from the floor. At a minimum, it is recommended that the materials be repaired and monitored. If removal is planned, extensive gross removal procedures are recommended. This appears to be a high traffic area.

				<u> </u>								
LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	QUANTITY	UNITS OF MEASURE	PIPE . ID	EXP POT	PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
along south & east walls	00-356608	50%	pipe covering	OMA	4 f	t. 4 in. 0	.D. HPS/F	27	111	\$36	\$22	\$58
along south & east walls	00-356608	50%	pipe covering	OMA		t. 6 in. 0					\$178	\$464
along south & east walls	00-356608	50%	pipe covering	- OMA	100 f	t. 12 in.	D.D HPS/F	27	111	\$2,202	\$1,693	\$3,895
closet next to south doorway-at ceiling	00-356608	50%	pipe covering	AMO	5 f	t. 6 in. 0	.D. HPS/R	27	111	\$65	\$41	\$106
closet west of elevator	00-356608	50%	pipe covering	OMA	10 f	t. 6 in. 0	D. HPS/F	27	111	\$130	\$81	\$211
south wall-above exit & elevator	00-356608	50%	pipe covering	AHO	20 f	t. 6 in. 0	D. HPS/F	27	111	\$260	\$162	\$422
east center area-next to east wall	00-356612	0%	wrapped cardboard/paper pipe	AMO	24 f	t. 6 in. 0	D. DW					
along south & east walls	00-356730	40%	pipe covering	OMA	90 f	t. 12 in. (D.D DW	27	111	\$1,982	\$1,524	\$3,506

AREA DESCRIPTION: 4th Floor-Part #21-Grain Hopper Room

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 49

06/09/89

ASBESTOS ASSESS. SURVEY

H⁴K Building #: 21 Project Number: 0980193E

Project: G. HEILEMAN BREVERY "E"
Date Inspected: 03/21/89

Inspector: TIM SWARTZ

Building Number: 21/22

Building Name: BREWHOUSE/STOCK CELLARS

SEATTLE, WASHINGTON Building Type: BREW/STOCK

Year Constructed: 1948

along south & east walls	19-356731		mjp on pipe covering	OHA	4 12 in. O.D.	DW	27 111	\$303	\$190	\$493
	19-356732 19-356733	40% 45%		•			27 111 27 111			ł
along south & east walls	22-356609	0%	mip on pipe covering	OMA	6 6 In. 0.0.		27 111	\$232	\$136	\$368
along south & east walls	22-356609 22-356610	60%	mjp on pipe covering	OMA	4 12 in. O.D.	HPS/R	27 111	\$303	\$190	\$493
	22-356611	10%			<u> </u>		27 111			

AREA COMMENTS

AREA # 06 TOTAL \$5,799 \$4,217 \$10,016

The materials are in good condition with minor contact and water damage. The materials are approximately 1' to 16' from the floor. At a minimum, it is recommended that the materials be repaired and monitored. If removal is planned, extensive gross removal procedures are recommended. This appears to be a low traffic

***	*****	AREA NUMBER: 07	AREA DESCRIPTION: 5th Floor-Part #21	AREA AVERAGE % ASBESTOS: 43%	****

LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	UNITS OF QUANTITY MEASURE	PIPE ID	EXP POT	PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
southwest area-by scales southeast corner southwest area-by scales	00-356613 00-356617 23-356614 23-356615 23-356616	10%	pipe covering wrapped cardboard/paper pipe mjp on pipe covering	OHA OHA OHA	8 ft. 4 in. O.D. 12 ft. 6 in. O.D. 2 4 in. O.D.		27 27 27	111	* \$156	\$45 \$97 \$31	\$116 \$253 \$87
southeast corner	24-356618 24-356619 24-356620		m]p on wrapped cardboard/paper	OHA	2 6 in. O.D.	DW	27 27	111 111 111	\$77	\$45	\$122

AREA COMMENTS

AREA # 07 TOTAL \$360 \$218 \$578

The materials are in good condition with minor contact and water damage. At a minimum, it is recommended that the materials be repaired and monitored. If removal is planned, glove bag removal procedures are recommended. This appears to be a low traffic area.

٠.	*****	AREA NUMBER: 08	AREA DESCRIPTION: Ground Floor	AREA AVERAGE % ASBESTOS: 4%	*****

LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	QUARTITY	UNITS OF MEASURE	PIPE ID	EXP POT	PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
spent grain room-south wall south stairwell-at ceiling stock cellar H-against east wall	03-356469 03-356469 03-356469 03-356470	0%	pipe covering pipe covering pipe covering	OMA OMA OMA	6 f	t. 12 in.	O.D RS/R O.D RS/R O.D RS/R	12	IV IV IV	\$330 \$132 \$881	\$102	\$584 \$234 \$1,558

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 50

ASBESTOS ASSEL / SURVEY

41-K Building #: 21

Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/21/89 Inspector: TIM SWARTZ Building Number: 21/22

Building Name: BREWHOUSE/STOCK CELLARS

SEATTLE, WASHINGTON

Building Type: BREW/STOCK

Year Constructed: 1948

03-356471 12 IV

AREA COMMENTS

AREA # 08 TOTAL \$1,343 \$1,033 \$2,376

The material is in good condition. The material is approximately 9' from the floor. At a minimum. it is recommended that the material be maintained and monitored. If removal is planned, glove bag removal procedures are recommended. This appears to be a high traffic area.

******** AREA NUMBER: 09 AREA DESCRIPTION: 2nd Floor AREA AVERAGE % ASSESTOS: % *********

LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	QUANTITY	UNITS OF MEASURE	PIPE ID	EXP POT	PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
north brew kettle south brew kettle mezzanine level-whirlpool tank	00-999999 00-999999 00-999999	X	boiler/tank insulation boiler/tank insulation boiler/tank insulation	OMB OMB		q.ft. q.ft. q.ft.				\$5,085 \$5,085 \$17,798	\$4,073 \$4,073 \$14,257	\$9,158 \$9,158 \$32,055

AREA COMMENTS

AREA # 09 TOTAL \$27,968 \$22,403 \$50,371

The material has a metal covering, making sample collection impossible. At a minimum, it is recommended that the material be maintained and monitored. If removal is planned, extensive gross removal procedures are recommended. This appears to be a high traffic area. This material has a stainless steel covering.

***** AREA NUMBER: 10 AREA DESCRIPTION: 3rd Floor-Tank Top Room AREA AVERAGE % ASBESTOS: % *****

LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&H CODE	UNITS OF QUANTITY MEASURE	PIPE ID	EXP POT	PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
mash tub adjunct cooker convertor tank caustic tank	00-99999 00-999999 00-999999	X	boiler/tank insulation boiler/tank insulation boiler/tank insulation boiler/tank insulation	OMB OMB OMB	152 sq.ft. 152 sq.ft. 152 sq.ft. 152 sq.ft.				\$4,294 \$4,294 \$4,294 \$4,294	\$3,440 \$3,440	\$7,734 \$7,734 \$7,734 \$7,734

AREA COMMENTS

AREA # 10 TOTAL \$17,176 \$13,760 \$30,936

The material has a metal covering, making sample collection impossible. At a minimum, it is recommended that the material be maintained and monitored. If removal is planned, extensive gross removal procedures are recommended. This appears to be a high traffic area.

> \$407,393 BUILDING # 21 TOTAL \$231,255 \$176,138

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 51